



M.S.O. Avionics Services Ltd

Light Aircraft Avionics Maintenance

P.O. Box 57208, 3313 Limassol – Cyprus

Tel. 357-99636393, Fax 357-25720700

PRICE LIST 2026

ITEM	DESCRIPTION	PRICE
ANNUALS / 100 HRS CHECKS		
1	Annual Check on single engine aircraft with one pitot-static system in accordance with the requirements of Aircraft Maintenance Programme, including pitot-static leak & calibration tests, check swing, radio license renewal, transponder, encoder, VOR, ILS & DME calibration checks, and issue of all necessary forms. <i>(No special test equipment included. Investigation and/or rectification of any defects found not included.)</i>	€ 325.00
2	Annual Check on twin engine aircraft with twin pitot-static systems in accordance with the requirements of Aircraft Maintenance Programme, including pitot-static leak & calibration tests, check swing, radio license renewal, transponder, encoder, VOR, ILS & DME calibration checks, and issue of all necessary forms. <i>(No special test equipment included. Investigation and/or rectification of any defects found not included.)</i>	€ 420.00
INSPECTIONS		
3	Aircraft electrical, radio, instrument & A/P systems inspection / function checks for the purpose of issuing of Certificate of Airworthiness, ARC or aircraft sales on single engine aircraft on multi-engine aircraft	€ 120.00 € 150.00
RADIOS		
4	Radio systems testing and adjusting using a Field Test Set per system <i>(Does not include rental fees, if any, of the Field Test Set or extra test sets like P/S tester)</i>	€ 60.00
5	Radio License renewal checks including recording of installed radios and filling of DCA form SF-35	€ 60.00
COMPASSES		
6	Compass Swing including compensation & adjustments, deviation form filling and issue of deviation card (not including cost of person in cockpit if required)	€ 145.00
7	Compass check swing	€ 60.00
8	Remake of Compass deviation card	€ 15.00
PITOT / STATIC		
9	Single system pitot-static leak test / height simulation in situ <i>(Pitot & static for 1 ASI, 1 ALT, 1 VSI)</i>	€ 50.00
10	Single system pitot-static leak & calibration test and issue of calibration form in situ <i>(Pitot & static for 1 ASI, 1 ALT, 1 VSI)</i>	€ 155.00
11	Single system pitot-static leak & calibration test and issue of calibration form in situ <i>(Pitot & static for G1000 or similar system plus stby instruments 1 ASI, 1 ALT)</i>	€ 215.00
12	Twin system pitot-static leak & calibration test and issue of calibration form in situ <i>(2 Pitots & statics for 2 ASI, 2 ALT, 2 VSI)</i>	€ 275.00
13	Single removed instrument leak test. <i>(Does not include removal of the instrument)</i>	€ 25.00
14	Single removed instrument leak & calibration test and issue of calibration form <i>(Does not include removal of the instrument)</i>	€ 60.00
15	Issue of pitot-static instrument single discrepancy card after calibration	€ 15.00
BATTERIES		
16	Battery charging including removal from aircraft & refitting	€ 30.00
17	Lead Acid Capacity testing including removal from aircraft & refitting	€ 90.00
18	New Lead Acid Battery filling with electrolyte, charging & fitting on aircraft	€ 30.00
19	Battery NiCd Periodic Testing (removal & refitting from a/c not included)	€ 60.00
20	Battery NiCd Regular Testing (removal & refitting from a/c not included)	€ 100.00
21	Battery NiCd Overhaul (removal & refitting from a/c not included)	€ 180.00
LABOUR		
22	General defect investigation / rectification Labour	€ 80.00
23	General Workshop Labour	€ 80.00
NOTES		
	Depending on the nature and time of the work to be done, an additional charge may be added for transportation purposes. Maintenance outside Cyprus will be charged according to situation. Prices may change without notice. Prices do not include VAT	